





PortA pullup must be set by soft
 PortB pullup must be set by soft
 each Port C pin must be set as input when not used
 PortB pullup must be set by soft

Compass Sensor Interface



PCB-E026V1A

Engineer: XE881C05	Title: SKI_PCB/ABU/Atmega/compass	Version: 30
Editor: SKI	Last Edit: Tuesday, September 4, 2001 5:39:12 pm	Sheet Name: Sheet1
Author: SKI	Project: SKI_PCB/ABU/Atmega/compass	Sheet: 1 of 1